



E83F


$S = 9 \text{ mA/V}$
 $V_{g1} = -2 \text{ V}$
 $R_i = 500 \text{ k}$
 $R_{eq} = 750 \Omega$
 $P_a = \text{max. } 2.1 \text{ W}$
 $\mu g_{2g1} = 34$

**E90F**


$S = 4.6 \text{ mA/V}$
 $V_{g1} = -7.7 \text{ V}$
 $R_i = 1.3 \text{ M}$
 $R_{eq} = 2.5 \text{ k}$
 $P_a = \text{max. } 2.6 \text{ W}$
 $\mu g_{2g1} = 50$

**E180F**


$S = 15.9 \text{ mA/V}$
 $\mu g_{2g1} = 50$
 $R_i = 90 \text{ k}$
 $P_a = \text{max. } 3 \text{ W}$
 $R_{eq} = 460$


**E280F**

$S = 26 \text{ mA/V}$
 $\mu g_{2g1} = 60$
 $R_i = 100 \text{ k}$
 $P_a = \text{max. } 4 \text{ W}$
 $R_{eq} = 220$


**E810F**

$S = 50 \text{ mA/V}$
 $\mu g_{2g1} = 57$
 $R_i =$
 $P_a = \text{max. } 5 \text{ W}$
 $R_{eq} = 100$







EAF41




EAF42



EAF42



EAF801



EBF2